

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

496  
ESE  
1/2-1  
0.767 mi.  
4049 ft.

TM #606  
BRIGHTON 2 & BRIGHTON BCH  
BROOKLYN, NY

NY Spills S104788471  
N/A

Relative:  
Higher

Actual:  
9 ft.

SPILLS:

Name: TM #606  
Address: BRIGHTON 2 & BRIGHTON BCH  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0005852 / 2001-05-08  
Facility ID: 0005852  
Facility Type: ER  
DER Facility ID: 216255  
Site ID: 265408  
DEC Region: 2  
Spill Cause: Unknown  
  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2000-08-16  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 2000-08-16  
CID: 257  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2000-08-16  
Spill Record Last Update: 2001-06-11  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: TONY LOPEZ  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL DEC INSPECTOR'S NOTES Sample results <1ppm. Cleanup, done. CON ED E2MIS REPORT 8-16-00 0842hrs. Undiaperable sheen on 400 gals. of water in TM606. Pressure tested unit found to be good. Oil level also is good. States no sewers or waterways are affected. Sample has been taken. Sheen may be food related to fried chicken store which leaves garbage on sidewalk in front of transformer and he sees dark stain running from street inot structure. Cement sump in structure. This structure was previously cleaned on 7-07-00 #132175 and when tested wa found to be <1ppm. Cleanup pending new test results. 8-17-00 Lab Seq#00-07862 <1ppm 1-26-01 1345hrs. Cleanup completed by double washing structure with slix. Liquids were removed by tnaker,soilds were removed by tanker. No leaking company equipment. Incident closed."  
Remarks: "sheen on 200gals of water - cleanup pending test results ref #132892"  
Not reported

All Materials:

Site ID: 265408  
Operable Unit ID: 826815

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Operable Unit: 01  
Material ID: 546991  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported